

## Description

Renovation and extension of existing nursing home from the 70's. The nursing home needed to be renovated and refurbished to meet current requirements with regard to carers' working conditions. The bathrooms had to be refurbished within the existing walls as no additional space was available.

## Pressalit Care's solution

- Tracks on 3 walls
- R3548 Support arms
- R4760 Wash basin bracket, gas
- R2050 Ergonomic wash basin
- R37 Dania toilet seat
- RT756 Shower mixer bracket
- Shower-/handrail system

## Effect

The out-of-date bathrooms were refurbished according to current legislation. The problem of limited space was overcome through the use of vertically and horizontally adjustable bathroom products. The bathrooms can be used by dependent as well as independent users and the flexible lay-out helps optimise carers' working condition.

## Architect

Hune og Elkjær  
Dronning Margrethesvej 71  
DK-8200 Århus N

## Installer

Bjerg VVS  
Tværvej 17  
DK-6880 Tarm

## Consulting engineer

Carl Bro A/S

## Builder

Egvad Kommune

